

Swamp's Diesel Performance

Competition Parts For Your Diesel

304-A Sand Hill Rd.

La Vergne, TN 37086

Tel 615-793-5573 or (866) 595-8724/ Fax 615-793-5572

Email: dave@swampsdiesel.com

Swamp's Diesel Performance defines CORE INJECTORS as those injectors which were most recently installed into your vehicle's engine. Injectors returned to us, which are out of a salvage yard, injectors which have been burned, or externally damaged, will NOT be suitable as cores. Any injector which has previously been disassembled will NOT be a suitable core injector. If you have any questions these restrictions to your core injectors, please don't hesitate to give us a call.

We DO NOT bill a core charge up front, when you purchase a set of fuel injectors. However, if a customer fails to return any core within 30 days of delivery, then the customer agrees to a \$1000 core charge. If, due to scheduling conflicts, installation of the new injectors will not occur in a reasonable amount of time, please CALL US, we may, at our discretion, extend your 30 day core return window to better suit your installation schedule.

Our core policy can be broken down into two sub-policies.

A) If you are purchasing STOCK injectors (AA, AB, AD, etc), then the following policy will be implemented.

As long as we receive injectors which meet our definition of CORE INJECTORS, no charges will be applicable, other than those outlined above.

B) If you are purchasing injectors SMALLER than 200cc (such as our 150's, or 175's), then the following core charges will be applicable.

Your cores will need to meet ALL of the stipulations outlined in our definition of "CORE INJECTORS, as well as being free of damages which may have occurred due to poor quality fuel being run through the injectors.

If your cores have been exposed to gasoline, water, or poor fuel filtration, then you can assume that all 8 of the plunger & barrel assemblies will be damaged, and will need to be replaced at a cost of \$480 per set.

Normal injector wear, to include poppet valve wear, fuel plate erosion, loss of internal spring tension, etc, is considered normal, and we repair/replace those parts on every set. Normal wear is not something we consider to be out of the ordinary, so no extra charges should be expected. Again, if you have any questions regarding our core policy, please don't hesitate to give us a call.